

FIG.3





Re: Mitsuo NAKAMURA Q95853
RUBBER MEMBER CONVEYING DEVICE AND RUBBER MEMBER SUPPLYING SYSTEM WITH THE SAME
Steven M. Gruskin, 202-293-7060
REPLACEMENT DRAWINGS
5 of 6

